

Example on plane failure

Slope strikes = N60E slope angle = 50 SE

Joint set dips = 40 direction of dip = S40E

Friction angle = 30

Determine if this joint set is able for plane failure or not, and give reasons.

